Provisional Inspection Per Cody

SIERRA SERVICE CENTER 296 E. FRY BLVD. SIERRA VISTA, AZ 85635 (520) 458-8136 JAY NORTH 2012 FORD F450 SUPER DUTY 1FT8W4DT6CEA88086

Odometer: 1

Cabin Interior



Turn Signals / Hazards/Interior

Technician Note: Interior turn signal indicators functioning as designed using both the interior multi-function turn signal stalk, and the hazard warning switch.



Mirrors (Interior & Exterior

Technician Note: No visibility issues to note from exterior side view, and interior rear view mirrors.



Interior Lighting

Technician Note: Interior map and dome lamps operating as intended using individual lamp switches, and door ajar switches.



Horn

Technician Note: Horn wiring, switches, relays, and sirens all functioning properly duringinspection.



Dash Warning Lights

Technician Note: No warning lamps illuminated.

Visibility



Windows and Windshield

Technician Note: Front windscreen showing to be free of cracks and chips. Side windows show to be all intact and fully operational using the drivers side master window switch, and each individual window switches on doors.

Turn Indicator & Hazard Lights

Technician Note: Front and rear turn signal indicators found to be functioning on all four corners as designed.

Tail Lights

Technician Note: No concerns from LED rear tail lamps and brake lamps at the time of inspection.

Head Lights

Technician Note: High and low beam headlamps fully functional using both dedicated headlamp switch, and high beam feature of multifunction indicator stalk.

Windshield Wiper Blades

Technician Note: No rips or tears from wiper blade rubber elements, wipers proving sufficient to properly clean front windscreen.

Engine Bay

Engine Oil

Technician Note: Engine oil level at acceptable levels based on manufacturer set levels. Engine oil condition inspected good based on mileagea and age.

Transmission Fluid

Technician Note: Transmission fluid level and condition found to be acceptable during inspection. (Please see "Engine Oil" tab for pictures)

Brake Fluid

Technician Note: Brake fluid level found to be acceptable based on visual inspection. Brake fluid condition appears to be clean and free of any contaminants.

Coolant

Technician Note: Engine coolant found to be at proper levels, condition visually appears to be satisfactory at time of inspection.

Radiator, Hoses, and Fans

Technician Note: Radiator core, upper and lower radiator hoses, Cooling fan assembly, and other associated coolant and heater hoses all appearing in good condition without any note leaking or swelling of rubber hoses or connections.

Power Steering System / Fluid

Technician Note: Power steering fluid level at manufacturers MAX markings, fluid condition does not show any burnt or dirty fluid. No concerns at this time.

Windshield Washer / Resevoir

Technician Note: Windshield washer reservoir found to be capable of holding washer fluid. Washer reservoir pumps, washer hoses, and washer nozzles all providing ability to properly clean windshield.

Drive Belt(s)

Technician Note: Engine serpentine drive belt not showing any irregularities nor cracking. Serpentine belt tensioner inspected and is providing proper tension at this time of inspection.

Engine Air Filter

Technician Note: Engine air filter showing minor accumulation of dust and slight debris, however not recommended for replacement at this time.

Battery Status

Technician Note: Vehicles 12V batteries testing at or above manufacturers specifications for battery voltage and amperage.


Schrader Valve Ports

Technician Note: No issues to note nor concerns from HVAC high and low side service ports.

Clutch Fluid (Manual Transmissions Only)

Technician Note: This vehicle is not equipped with a manual transmission.

Undercarriage / Steering / Suspension



- Driveability
- Visible Leaks
- **Other Technician Concerns**

Report Prepared On 3/7/2024 ©2024 BOLT ON TECHNOLOGY